

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14567	Main Street: E_TREMONT_AV		Cross	Cross Street: LYNDHURST_AV			Location:		S
ADA ID: 49516693EC99	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance:			nce: N	o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data			Compliance Description		Data
STORY AND		Remove & Replace Entire Ram	D .	N/A	Ramp Length (in)	44.0	N/A	Grade Break?	N/A
	1. 7			Yes	Ramp Width (in)	53.0	N/A	Grade Break Slope (%)	0.0
Stand and a stand	ANDER			Yes	Ramp Slope (%)	6.1	N/A	Grade Break XSlope (%)	0.0
	In its			No	Ramp XSlope (%)	3.5			
A CARACTER AND A CARACTER ANTE ANTE ANTE ANTE ANTE ANTE ANTE ANTE	(Ata	6		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	the start	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	Pality - 10	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
A REAL PROPERTY OF				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	1 . T .			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	11			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
O St. The A	1 Prov			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	1. 2.			N/A	Painted X Walk1?	No		Road Slope (%)	5.2
Street 1 Name LY	NDHURST AV	_			X Walk 1 Direction	To NW		Road X Slope (%)	2.8
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	5.2	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	2.8	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	36.6

