

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 8030 Main Street: RUTGERS\_AV Cross Street: W\_SUGAR\_CREEK\_RD Location: NW **Severity Score:** ADA ID: 496D6BF2AC6D Ramp Type: Para Initial Pass/Fail: Fail **Overall Compliance: No** 25

Codes/Mitigation Info/Possible Solution



**RUTGERS AV** Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions:	Cor
Remove & Replace Entire Ramp.	N/A
	Yes
	Yes
	Yes
	N/A
	N/A
Surveyor Notes:	N/A
LT RP < 5%	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
R304.3.2	N/A
	N/A
	N/A

	4111			18 11
		FOR IALL SERVICE FIRSTER pure	M.	
		-		
-				
***				

Total Cost:



1600.00

Field Measurements/Component Compliance									
Compl	iance Description	Data	Compl	iance Description	Data				
N/A	Ramp Length LT (in)	62.5	N/A	Ramp Length RT (in)	63.0				
Yes	Ramp Width LT (in)	50.0	Yes	Ramp Width RT (in)	50.0				
Yes	Ramp Slope LT (%)	0.3	No	Ramp Slope RT (%)	15.0				
Yes	Ramp XSlope LT (%)	1.3	Yes	<b>Yes</b> Ramp XSlope RT (%)					
N/A	Landing Length (in)	N/A	N/A	N/A DWS Provided?					
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A				
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A				
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A				
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A				
N/A	Shared Landing?	N/A							
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A				
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A				
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A				
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A				
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A				
	X Walk 1 Slope (%)	0.0		X Walk 2 Slope (%)	N/A				
	X Walk 1 X Slope (%)	5.0		X Walk 2 X Slope (%)	N/A				
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A				
	Road Slope (%)	N/A	N/A	Clear Space?	N/A				
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A				
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A				
	Obstruction Type			Storm Grate/Utility Type					
		N/A			N/A				
			Yes	Surface Condition? (G/P)	Good				
			N/A	Curb Slope (%)	28.8				