

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

10.3

6.8

N/A

No

To N

Intersection ID: N/A Main Street: PROVIDENCE\_PROMINADE\_DRCross Street: HENRY\_QUINCY\_WY Location: SW

ADA ID: 4A6CD955C14D Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

No

No

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

Flare Traversable RT?

Data

61.0

47.0

N/A

Yes

To NE



Street 1 Name PROVIDENCE PROMENADE DR
Stop Condition-Street 2 Name HENRY QUINCY WY
Stop Condition-Street 1 StopSign

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

No Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A Gutter Ponding? N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/ N/ N/

N/A

Compliance Description

Ramp Length (in)

Total Cost: \$ 3200.00

<b>/</b> A	X Walk 1 Width (in)	52.0	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	5.5		X Walk 2 Slope (%)	3.2
	X Walk 1 X Slope (%)	6.3		X Walk 2 X Slope (%)	6.9
/ <b>A</b>	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	10.0	N/A	Clear Space?	N/A
	Road X Slope (%)	3.9	N/A	Clear Space to XWalk (in)	N/A
/ <b>A</b>	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good





