

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14400	Main Street: BERKELEY_AV			Cross Street: DILWORTH_RD				Location:	SE
ADA ID: 4C18221CCB48 Ramp Type: Directional1		Initial F	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	and the second	Possible Solutions:	Compliance Description			Data	Data Compliance Description		
		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	54.0	N/A	Grade Break?	N/A
The second se	Charter of the second			Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
	100			Yes	Ramp Slope (%)	6.6	N/A	Grade Break XSlope (%)	0.0
	Constant of			No	Ramp XSlope (%)	5.2			
the second se	1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	A CRA			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	S. Weight	NO CURB LINE		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
E. S.	1			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	17 S			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	A. S.			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	and the second	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
The A AND S.		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
and the second s	3.5- A			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	La L			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	NE AS			N/A	Painted X Walk1?	No		Road Slope (%)	8.0
Street 1 Name BE	RKELEY AV				X Walk 1 Direction	To NW		Road X Slope (%)	1.0
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	8.0	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.0	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	2.4

