

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16179	Main Str	Main Street: HERTFORD_RD			Cross Street: SHERWOOD_AV				NW	
ADA ID: 4F983ABE4245	Ramp Ty	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				37.5	
Codes/Mitigation Info/Possible Solution				Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 37.5 Field Measurements/Component Compliance						
The state is the		Possible Solutions:						liance Description	Data	
	A. 1	Remove & Replace Entire Ram	`	N/A	Ramp Length (in)	45.0	N/A	Grade Break?	N/A	
The factor of	1 and and			Yes	Ramp Width (in)	48.0		Grade Break Slope (%)	0.0	
	8			No	Ramp Slope (%)	9.7	N/A	Grade Break XSlope (%)	0.0	
17.9 Dan 11				No	Ramp XSlope (%)	12.8				
				N/A	Flare Type LT	N/A		Flare Type RT	N/A	
	1 1			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
B	AND P	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
E	No Alla	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
Star Star		N/A		N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
A CONTRACTOR				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
A LAND A				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
the second se	NO SA	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A		DWS Offset LT (in)	N/A	
		R304.2.2, R304.5.3		N/A	Shared Landing?	N/A		DWS Offset RT (in)	N/A	
Televis III		1,304.2.2, 1,304.3.3		N/A	Gutter Ponding?	0.0		Gutter Slope (%)	N/A	
1 In Parts	A AN AN			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
1 7 Bar 100	al al a se			N/A	Painted X Walk1?	No		Road Slope (%)	6.6	
Street 1 Name	HERTFORD RD	1			X Walk 1 Direction	ТоЕ		Road X Slope (%)	5.8	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	6.6	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	5.8	N/A	Storm Grate/Utility Hazard?	N/A	
F				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	23.8	
							• • • • •			

