

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.3

7.4

N/A

Good

Intersection ID: N/AMain Street:LANGWELL_LNCross Street:INVERNESS_BAY_RDLocation:NEADA ID: 4FB60D016D9ARamp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:33.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Flare Type RT

Data

50.0

47.5

N/A

1.0

No

N/A

0.2

2.5

N/A

N/A

N/A

N/A

N/A

To SW



Street 1 Name	LANGWELL LN
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

russible solution	i ieiu iviea	3
Possible Solutions:	Compliance Description	
Remove & Replace Entire Ramp.	N/A Ramp Length (in)	
·	No Ramp Width (in)	
	N/A Flare Type LT	
	N/A Flare Slope LT (%)	
	N/A Flare Traversable LT?)
	N/A Landing Length (in)	
Surveyor Notes:	N/A Landing Width (in)	
N/A	N/A Landing Slope (%)	
	N/A Landing X Slope (%)	
	N/A Landing Curb? (Y/N)	
	N/A Shared Landing?	
PROW/ADA:	N/A Gutter Ponding?	
Not Found, R304.5.1, R304.5.3	N/A Gutter Lip Ht (in)	
, , , , , , , , , , , , , , , , , , , ,	N/A Painted X Walk1?	
	X Walk 1 Direction	
	N/A X Walk 1 Width (in)	
	X Walk 1 Slope (%)	
	X Walk 1 X Slope (%)	
	N/A Ramp inside XWalk1?)
	Road Slope (%)	
	Road X Slope (%)	
	N/A Any Obstructions?	
	Road X Slope (%)	





Total Cost:



1850.00

Obstruction Type