

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14373Main Street: EAST_BVCross Street: LYNDHURST_AVLocation:NEADA ID: 4FB6C423A73CRamp Type: Directional1Initial Pass/Fail: PassOverall Compliance: NoSeverity Score: 0.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name EAST BV
Stop Condition-Street 1 None
Street 2 Name N/A
Stop Condition-Street 2 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

N
Y
N
Surveyor Notes:

N/A

Y
PROW/ADA:

R304.5.3

Total Cost: \$ 1600.00

| Compliance Description Data | | | Compliance Description Data | | |
|-----------------------------|-----------------------|-------|-----------------------------|-----------------------------|------|
| N/A | Ramp Length (in) | 67.0 | Yes | Grade Break? | Yes |
| Yes | Ramp Width (in) | 72.0 | No | Grade Break Slope (%) | 8.3 |
| Yes | Ramp Slope (%) | 6.8 | Yes | Grade Break XSlope (%) | 0.5 |
| No | Ramp XSlope (%) | 2.5 | | | |
| Yes | Flare Type LT | N/A | Yes | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | No | N/A | Flare Traversable RT? | No |
| Yes | Landing Length (in) | 61.0 | Yes | DWS Provided? | Yes |
| Yes | Landing Width (in) | 72.0 | Yes | DWS Contrast? | Yes |
| Yes | Landing Slope (%) | 1.9 | Yes | DWS Length (in) | 25.0 |
| Yes | Landing X Slope (%) | 0.2 | Yes | DWS Full Width? | Yes |
| N/A | Landing Curb? (Y/N) | N/A | Yes | DWS Offset LT (in) | 0.0 |
| N/A | Shared Landing? | No | Yes | DWS Offset RT (in) | 17.0 |
| Yes | Gutter Ponding? | No | Yes | Gutter Slope (%) | 3.9 |
| Yes | Gutter Lip Ht (in) | 0.0 | Yes | Gutter X Slope (%) | 1.4 |
| N/A | Painted X Walk1? | No | | Road Slope (%) | 2.2 |
| | X Walk 1 Direction | To SW | | Road X Slope (%) | 0.7 |
| | X Walk 1 Width (in) | N/A | | Clear Space? | Yes |
| | X Walk 1 Slope (%) | 2.2 | N/A | Clear Space to XWalk (in) | N/A |
| | X Walk 1 X Slope (%) | 0.7 | Yes | Storm Grate/Utility Hazard? | No |
| N/A | Ramp inside XWalk1? | N/A | | Storm Grate/Utility Type | |
| Yes | Any Obstructions? | No | | | N/A |
| | Obstruction Type | | Yes | Surface Condition? (G/P) | Good |
| | | N/A | N/A | Curb Slope (%) | 5.8 |
| | | | | | |





