cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Surface Condition? (G/P)

Good

Intersection ID: 8442 Mai	n Street: BROOKSHIRE_BV	Cross Street	: HONEYWOOD_AV		Location:	S
	Ramp Type: Perp		Initial Pass/Fail: Fail Overall Complianc		e: No Severity Score:	21.25
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance				
R MIN A COMM	Possible Solutions:				Compliance Description Data	
Anton a state of the	Remove & Replace Entire Ramp	N/A	Ramp Length (in)	50.0 N	No Ramp Slope (%)	9.6
		No	Ramp Width (in)	38.0 Y	Yes Ramp XSlope (%)	0.6
6.	the second s	N/A	Flare Type LT	N/A N	N/A Flare Type RT	N/A
Siloora . t	1 to	N/A	Flare Slope LT (%)	N/A N	N/A Flare Slope RT (%)	N/A
A AD BUT A	6.5	N/A	Flare Traversable LT?	N/A N	N/A Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A N	N/A DWS Provided?	N/A
8	Surveyor Notes:	N/A	Landing Width (in)	N/A N	N/A DWS Contrast?	N/A
	N/A	N/A	Landing Slope (%)	N/A N	N/A DWS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A N	N/A DWS Full Width?	N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		N/A	Landing Curb? (Y/N)	N/A N	N/A DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A		
and the second	PROW/ADA:	N/A	Gutter Ponding?	N/A N	N/A Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.2.2	N/A	Gutter Lip Ht (in)	0.5 N	N/A Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No N	N/A Painted X Walk2?	N/A
	1		X Walk 1 Direction	To E	X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A N	N/A X Walk 2 Width (in)	N/A
Street 1 Name HONEYWOOD	AV		X Walk 1 Slope (%)	1.9	X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 StopS			X Walk 1 X Slope (%)	0.2	X Walk 2 X Slope (%)	N/A
	N/A	N/A	Ramp inside XWalk1?	N/A N	N/A Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A		Road Slope (%)	0.2 N	N/A Clear Space?	N/A
			Road X Slope (%)	1.9 N	N/A Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	-	N/A Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	1850.00	Obstruction Type		Storm Grate/Utility Type	
			2.	N/A		N/A

Yes

