

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30005	Main Street: BACKWATER_DR			Cross Street: BRIGHTHAVEN_LN					Location:	SE
ADA ID: 4FDC38E74D94	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	Possible Solutions:				Compliance Description			Data Compliance Description		
	ATTONIC ATTACAN	Remove & Replace Curb Ramp W Two New Directional Ramps or Equivalent.	Ramp Wi	th	N/A	Ramp Length (in)	71.0	Yes	BlendTrans Slope (%)	4.0
Carlo Carlo					Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	8.3
at the second se			•		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
5. ELSON		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Et.	a think	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6. E				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	A North Cart				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
						X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
and the second second					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	BRIGHTHAVEN LN					X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign					X Walk 1 X Slope (%)	4.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A					Road Slope (%)	4.2		Clear Space?	N/A
						Road X Slope (%)	0.6	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 3200	0.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

17.0