

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31904	4 Main St	Main Street: CHAPECLANE_RD			PALOMAR_MOUNTAIN	Location:	SW		
ADA ID: 5009E3A8D4	36 Ramp T	Ramp Type: BlendTrans2			ail: Fail Overall C	o Severity Score:	8.75		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data			Compliance Description		Data
		Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	96.0	Yes	BlendTrans Slope (%)	4.8
		Two New Directional Ramps or		No	Ramp Width (in)	44.0	Yes	BlendTrans XSlope (%)	0.3
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
PALOMAR MOUNTAIN				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
PALOMAR		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
THE WARD		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Aller in the	•		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A	N/A	DWS Offset (III)	N/A
A state by the	Cold Passage The			N/A	6	N/A	N/A		N/A
		PROW/ADA:			Gutter Ponding?			Gutter Slope (%)	
		R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	ALL ALL	8		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
the second se					X Walk 1 Direction	To E		X Walk 2 Direction	To N
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	CHAPECLANE RD				X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	3.2
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	0.4
Street 2 Name	PALOMAR MOUNTAIN DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign				Road Slope (%)	1.5		Clear Space?	N/A
					Road X Slope (%)	3.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	00.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

N/A

Surface Condition? (G/P)

Curb Slope (%)

Good

3.4