## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	ction ID: N/A Main Street: W_TYVOLA_RD				Street:	N/A	Location:	N		
ADA ID: 50F2135135B6	Ramp Type: BlendTrans1			Initial	Initial Pass/Fail: Fail Overall Compliance: No					1.25
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
Possible Solutions:					Compliance Description		Data Compliance			Data
		Remove & Replace Curb	Ram	n With	N/A	Ramp Length (in)	36.0	1	BlendTrans Slope (%)	1.9
		Two New Directional Ram		•	Yes	Ramp Width (in)	48.0		BlendTrans XSlope (%)	4.2
		Equivalent.		-	N/A	Flare Type LT	N/A		Flare Type RT	N/A
					N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
	Ar I				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
A Real Providence and	验. / 物)	Surveyor Notes:			N/A	Landing Length (in)		N/A	DWS Provided?	N/A
b. b.	1 -				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1 70%	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	1 Adam				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
L K					N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A
5 K	<u>6</u>				N/A	Shared Landing?	N/A			
the state		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A A A A A A A A A A A A A A A A A A A	<u>ь</u> .	Not Found, R304.5.3			N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
the second s	Not 1 Ound, 1004.0.0			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Sur C.					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
e e					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	ENTRANCE	-				X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign					X Walk 1 X Slope (%)	3.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	. c N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign					Road Slope (%)	3.5		Clear Space?	N/A
						Road X Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

21.8