## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18627	rsection ID: 18627 Main Street: CEDARBARK_DR		Cross	Cross Street: CLIFTON_MEADOW_DR				Location:	E
ADA ID: 515772A2373E	D: 515772A2373E Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
1 2 1/ 10		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	37.0	No	Ramp Slope (%)	9.7
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.0
and the second s				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	1 Martin Share			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
67	1/ Martin San Carlos			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and a state	10	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	· · · · · ·	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Contraction of the second seco	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	S		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
BUTTE & PRO				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
2/1/ 000	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
R304.2.2, R304.5.3				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	CEDAR BARK DR				X Walk 1 Slope (%)	5.3		X Walk 2 Slope (%)	1.9
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	0.6
Street 2 Name	CLIFTON MEADOW DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	1.2	N/A	Clear Space?	N/A
					Road X Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

