

Access Compliance Report Public Rights-of-Way (Curb Ramps)



						Lesstien	0
Intersection ID: 14360	Main Street: BALDWIN_AV		Cross Street: MAIN_ST			Location:	S
ADA ID: 5207674FD0FB F	5207674FD0FB Ramp Type: BlendTrans2		nitial Pass/Fail: Fail Overall Compliance:			o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance				
	Possible Solutions:	Co	Compliance Description		Data Compliance Description		Data
BRIDLAS	Remove & Replace Curb Ramp	With N//	A Ramp Length (ii	in) 45.0	Yes	BlendTrans Slope (%)	3.9
	Two New Directional Ramps or	Ye	Ramp Width (in	n) 48.0	No	BlendTrans XSlope (%)	2.6
	Equivalent.	N//	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N//	Flare Slope LT	(%) N/A	N/A	Flare Slope RT (%)	N/A
the second se	The second se	N//	Flare Traversab	ble LT? N/A	N/A	Flare Traversable RT?	N/A
the second second	A 8	N//	Landing Length	n (in) N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N//	Landing Width ((in) N/A	N/A	DWS Contrast?	N/A
	N/A	N//	Landing Slope ((%) N/A	N/A	DWS Length (in)	N/A
		N//	Landing X Slope	e (%) N/A	N/A	DWS Full Width?	N/A
		N//	Landing Curb?	(Y/N) N/A	N/A	DWS Offset (in)	N/A
		N//	A Shared Landing	g? N/A			
A CARL CALL AND A LOS	PROW/ADA:	N//	Gutter Ponding)? N/A	N/A	Gutter Slope (%)	N/A
ALL ALLAND	R304.5.3	N//	Gutter Lip Ht (in	n) N/A	N/A	Gutter X Slope (%)	N/A
and and and	10.	N//	A Painted X Walk	.1? No	N/A	Painted X Walk2?	N/A
and the second			X Walk 1 Directi	tion To NE		X Walk 2 Direction	N/A
The Marine D			X Walk 1 Width	(in) N/A		X Walk 2 Width (in)	N/A
Street 1 Name M	MAIN ST		X Walk 1 Slope	e (%) 6.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1 St	StopSign		X Walk 1 X Slop	pe (%) 2.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A	N//	A Ramp inside XV	Walk1? N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A		Road Slope (%)) 2.9		Clear Space?	N/A
			Road X Slope (6.6	N/A	Clear Space to XWalk (in)	N/A
		N//	Any Obstruction	ns? N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	3200.00	Obstruction Typ	be		Storm Grate/Utility Type	
				N/A			N/A







Yes

N/A

Surface Condition? (G/P)

Curb Slope (%)

Good

0.8