

| | | | | |
|------------------------|-------------------------------|----------------------------------|------------------------|----------------------|
| Intersection ID: 28287 | Main Street: BRANDON_BROOK_DR | Cross Street: OLD_ARDREY_KELL_RD | Location: | SE |
| ADA ID: 525A61025305 | Ramp Type: Perp | Initial Pass/Fail: Fail | Overall Compliance: No | Severity Score: 37.5 |

| Codes/Mitigation Info/Possible Solution | Field Measurements/Component Compliance |
|---|---|
| <p>1. Code 100: No visible signs of corrosion or damage.</p> <p>2. Code 101: Minor surface corrosion, no structural impact.</p> <p>3. Code 102: Moderate surface corrosion, some pitting.</p> <p>4. Code 103: Severe surface corrosion, significant pitting.</p> <p>5. Code 104: Corrosion with visible structural damage.</p> <p>6. Code 105: Severe corrosion, structural failure imminent.</p> | <p>1. Field Measurements: Visual inspection, pH testing, corrosion rate measurements.</p> <p>2. Component Compliance: Verify material specifications, check for proper installation, ensure proper maintenance.</p> |



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

| Possible Solutions: | | | Compliance | Description | Data | Compliance | Description | Data |
|--|--|--|-------------|-----------------------|-------|------------|-----------------------------|------|
| Remove & Replace Entire Ramp. | | | N/A | Ramp Length (in) | 94.0 | No | Ramp Slope (%) | 9.1 |
| | | | Yes | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 8.8 |
| | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | N/A | Shared Landing? | N/A | | | |
| | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| Surveyor Notes: N/A | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | | | | X Walk 1 Direction | To NW | | X Walk 2 Direction | N/A |
| | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | | | | X Walk 1 Slope (%) | 6.6 | | X Walk 2 Slope (%) | N/A |
| | | | | X Walk 1 X Slope (%) | 3.0 | | X Walk 2 X Slope (%) | N/A |
| | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | N/A | | | N/A |
| | | | | | | Yes | Surface Condition? (G/P) | Good |
| | | | Total Cost: | | | \$ | 1850.00 | |
| PROW/ADA: | | | | | | | | |
| Not Found, R304.2.2, R304.5.3 | | | | | | | | |

Total Cost: \$ 1850.00

