

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 22558	Main Street: FERNBANK_DR			Cross Street: NEWGATE_CT				Location:	NE
ADA ID: 52D82531D059	Ramp T	Ramp Type: BlendTrans2			nitial Pass/Fail: Fail Overall Compliance: No				25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	10.38	Possible Solutions:		Compliance Description Data			Compliance Description Data		
Tester	A. C.	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	24.0	Yes	BlendTrans Slope (%)	1.9
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	8.9
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
STAD -	NY TANK			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	A A a			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	4	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	21	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
ACES -	X CO			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	A State			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
La sala a les	A AL AND			N/A	Shared Landing?	N/A			
STAR SAL		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	1 million				X Walk 1 Direction	To NW		X Walk 2 Direction	To S
A A CONTRACTOR AND A PROVIDENCE					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	NEWGATE CT	_			X Walk 1 Slope (%)	6.2		X Walk 2 Slope (%)	1.0
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	3.9		X Walk 2 X Slope (%)	7.0
Street 2 Name	ERNBANK DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	6.5		Clear Space?	N/A
					Road X Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

18.8