## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12741	Main Street: E_6TH_ST			Cross Street: N_ALEXANDER_ST				Location:	S
ADA ID: 535F27181205	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: N					
			Inntiante						10.70
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance   Compliance Description Data					
	A MAD	Possible Solutions:		Compliance Description			Data Compliance Description		
	A MARINA	Remove & Replace Curb Ramp W	Vith	N/A	Ramp Length (in)	80.0	No	Ramp Slope (%)	10.2
	515.5	Two New Directional Ramps or		Yes	Ramp Width (in)	49.0	No	Ramp XSlope (%)	3.2
	Color M	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Marine Marine			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	-11/05			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A Starting of the second se	<u>e</u>			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
6. / V		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
<b>人</b>	ALCONT OF	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6	A HAR			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
St Barrow	Big VIII	8		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 and a			N/A	Shared Landing?	N/A			
	1. 10. 10	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	1.5	N/A	Gutter X Slope (%)	N/A
4 / 1 - 30 /	y extin	Not 1 Julia, No04.2.2, No04.5.5		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
1 1 and	6 . 4 M			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	E 6TH ST	-		N/A	X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	0.4
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	2.9
Stop Condition-Street 2	N ALEXANDER ST			NI/A	,	0.1 N/A	N/A	,	2.9 N/A
				N/A	Ramp inside XWalk1?			Ramp inside XWalk2?	
Stop Condition-Street 1	StopSign				Road Slope (%)	2.9	N/A	Clear Space?	N/A
					Road X Slope (%)	0.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

