cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24384	24384 Main Street: BIRNEN_DR			Cross	Street:	N_VICKSBURG_PARI	Location:	S		
ADA ID: 54766C0A693	93B Ramp Type: BlendTrans2			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	E C C C C C C C C C C C C C C C C C C C	Possible Solutions:			Compliance Description		Data Compliance Description		Data	
Content and		Remove & Replace Cu	o Ram	p With	N/A	Ramp Length (in)	47.0	Yes	BlendTrans Slope (%)	3.8
R		Two New Directional Ra			No	Ramp Width (in)	47.0	Yes	BlendTrans XSlope (%)	1.1
		Equivalent.			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
and the second sec					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		NOLNDG			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
~ ~ ~					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
R ST	A CAR				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
	100	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		,			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
						X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
						X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	BIRNEN DR	-				X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	0.4
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	0.8
Street 2 Name	N VICKSBURG PARK CT				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign					Road Slope (%)	2.2		Clear Space?	N/A
						Road X Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A		,	N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

6.6