cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16756 Main Street: KELLY_ST C						SUMMEY_AV	Location:	SE		
ADA ID: 54A265A42C8E Ramp Type: BlendTrans2			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
6		Possible Solutions:			Compliance Description		Data Compliance Description		liance Description	Data
		Remove & Replace Curb	Ramp	o With	N/A	Ramp Length (in)	63.0	Yes	BlendTrans Slope (%)	4.1
		Two New Directional Ran Equivalent.	Ramps or		No	Ramp Width (in)	41.0	No	BlendTrans XSlope (%)	3.2
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	The state				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
E. Cor	- And				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
And the A				N/A	Shared Landing?	N/A				
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R3	04.5.3	5	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	and the	, ,			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
THE Strong to Marine					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	KELLY ST					X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A					Road Slope (%)	1.0		Clear Space?	N/A
						Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

11.2