

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17421	Main Street: CHILTON_PL			Cross Street: SHARON_RD				Location:	SW
ADA ID: 54A3A4A305D7	Ramp Type: BlendTrans2			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Entrement and the second		Possible Solutions:		Compliance Description			Data Compliance Description		Data
	LE CENTRON LINE	Remove & Replace Curt	Ramp With	N/A	Ramp Length (in)	107.0	Yes	BlendTrans Slope (%)	2.3
		Two New Directional Ram		No	Ramp Width (in)	38.0	No	BlendTrans XSlope (%)	5.5
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		Surveyor Notes:		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A		()	
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R30	453	N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
and the second se	NE 18 SAL		4.0.0	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	Yes
and the second second	A Mark				X Walk 1 Direction	To E		X Walk 2 Direction	To N
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	108.0
Street 1 Name	SHARON RD	-			X Walk 1 Slope (%)	4.8		X Walk 2 Slope (%)	0.2
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	4.7
Street 2 Name	CHILTON PL			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 2	StopSign				Road Slope (%)	3.2		Clear Space?	N/A
,					Road X Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 3200.0		Obstruction Type			Storm Grate/Utility Type	
				-		N/A			N/A
							1		







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

17.7