

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4005Main Street:DOWNING_CREEK_DRCross Street:SHOREHAVEN_CTLocation:SEADA ID: 54B1755C0D76Ramp Type:Directional1Initial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

ADA ID: 54B1755C0D76	Ramp Ty	/pe: Directional1		Initial F	Pass/Fa	ail: Fail Overall	Compliar	rce: N	o Severity Score:	10		
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance						
		Possible Solutions:			Comp	liance Description	Data	Comp	liance Description	Data		
		Remove & Replace Entire I	Ramp.	•	N/A	Ramp Length (in)	29.0	N/A	Grade Break?	N/A		
					No	Ramp Width (in)	44.0	N/A	Grade Break Slope (%)	0.0		
					Yes	Ramp Slope (%)	5.6	N/A	Grade Break XSlope (%)	0.0		
					No	Ramp XSlope (%)	3.1					
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
DOWNING_GRE	EN NE				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0		
		Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
│		N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A		
					N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A		
💆					N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A		
🐉					N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A		
		PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A		
Shoran Car		R304.5.1, R304.5.3			N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A		
® /					N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A		
					N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A		
]			N/A	Painted X Walk1?	No		Road Slope (%)	3.1		
Street 1 Name	SHOREHAVEN CT					X Walk 1 Direction	To W		Road X Slope (%)	6.7		
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A		
Street 2 Name	N/A					X Walk 1 Slope (%)	3.1	N/A	Clear Space to XWalk (in)	N/A		
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	6.7	N/A	Storm Grate/Utility Hazard?	N/A		
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type			
					N/A	Any Obstructions?	N/A			N/A		
		Total Cost:	\$ 1	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good		
							N/A	N/A	Curb Slope (%)	12.0		





