

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.8

3.1

N/A

No

To SE

N/A

0.7

3.5

N/A

N/A

N/A

N/A

N/A

Good

Main Street: PROVIDENCE LN WEST Intersection ID: 23341 **Cross Street: LYNROSE CT** Location: N Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 22.5 ADA ID: 55A60F01A92C Ramp Type: PerpDiag

Compliance Description

Ramp Length (in)

N/A

Codes/Mitigation Info/Possible Solution

None

Field Measurements/Component Compliance

No

Compliance Description

Ramp Slope (%)

Data

73.0

N/A

Yes

Surface Condition? (G/P)



Street 1 Name **PROVIDENCE LN WEST** Stop Condition-Street 2 LYNROSE CT Street 2 Name Stop Condition-Street 1 StopSign Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost: 3200.00

No Ramp XSlope (%) No Ramp Width (in) 47.0 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A **DWS Provided?** Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? X Walk 1 Direction To SW X Walk 2 Direction N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) 0.5 X Walk 2 Slope (%) X Walk 1 X Slope (%) 0.4 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? Road Slope (%) 0.3 N/A Clear Space? N/A Road X Slope (%) 2.2 Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? **Obstruction Type** Storm Grate/Utility Type





