

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11265	Main Street: N_TRYON_ST			Street:	WADSWORTH PL	Location:	Е			
ADA ID: 579717FD80DF		Ramp Type: Directional1			Initial Pass/Fail: Pass Overall Compliance: No				5.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
Possible Solutions:			Compliance Description Data Compliance Desc					Dete		
	10						1		Data	
		Remove & Replace Entire Ramp	).	N/A	Ramp Length (in)	112.0	Yes	Grade Break?	Yes	
		Gutter Ponding Observed.		Yes	Ramp Width (in)	58.5	Yes	Grade Break Slope (%)	1.8	
	1/1/10			Yes	Ramp Slope (%)	5.5	Yes	Grade Break XSlope (%)	0.7	
	12 0 0 5 30			No	Ramp XSlope (%)	2.6				
G S S	X A CONTROL S			No	Flare Type LT	N/A	Yes	Flare Type RT	N/A	
	A State State			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
5. 53 5		Surveyor Notes:		N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
		N/A		Yes	Landing Length (in)	70.5	Yes	DWS Provided?	Yes	
E B	a state 2			Yes	Landing Width (in)	60.0	Yes	DWS Contrast?	Yes	
				Yes	Landing Slope (%)	0.8	Yes	DWS Length (in)	24.0	
	A			Yes	Landing X Slope (%)	0.7	Yes	DWS Full Width?	Yes	
190	Contraction of the second	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	0.0	
	1 Page 1	R304.5.3, R304.2.3, R302.7		N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	13.0	
	1 1 1 1 1	· ·		No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	0.0	
	3 1 16			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.0	
At a start of the second se				N/A	Painted X Walk1?	Yes		Road Slope (%)	3.0	
Street 1 Name	WADSWORTH PL				X Walk 1 Direction	To SW		Road X Slope (%)	1.2	
Stop Condition-Street 1	Signal				X Walk 1 Width (in)	118.5		Clear Space?	Yes	
Street 2 Name	N/A				X Walk 1 Slope (%)	3.0	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.2	Yes	Storm Grate/Utility Hazard?	No	
				Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type		
				Yes	Any Obstructions?	No			N/A	
		Total Cost: \$	2100.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	1.9	

