

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 52839 Main Street: DOCIA CROSSING RD Cross Street: ROBERT_HELMS_RD Location: SE **ADA ID: 5904BB04D0EA** Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 1.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



DOCIA CROSSING DR Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

| Possible Solutions: | | | | | |
|-------------------------------|--|--|--|--|--|
| Remove & Replace Entire Ramp. | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| * | | | | | |
| | | | | | |
| Surveyor Notes: | | | | | |
| N/A | | | | | |
| | | | | | |
| | | | | | |
| DDOW/ADA | | | | | |
| PROW/ADA: | | | | | |
| R304.5.3 | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

Total Cost: 1850.00

| Field Measurements/Component Compliance | | | | | | |
|---|-----------------------|-------|------------------------|-----------------------------|------|--|
| Comp | liance Description | Data | Compliance Description | | Data | |
| N/A | Ramp Length (in) | 142.0 | Yes | Ramp Slope (%) | 6.4 | |
| Yes | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 2.6 | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| N/A | Shared Landing? | N/A | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A | |
| | X Walk 1 Direction | To W | | X Walk 2 Direction | N/A | |
| N/A | X Walk 1 Width (in) | 111.5 | N/A | X Walk 2 Width (in) | N/A | |
| | X Walk 1 Slope (%) | 1.4 | | X Walk 2 Slope (%) | N/A | |
| | X Walk 1 X Slope (%) | 3.2 | | X Walk 2 X Slope (%) | N/A | |
| N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A | |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A | |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | N/A | | | N/A | |
| | | | Yes | Surface Condition? (G/P) | Good | |





