

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

25.5

48.0

8.3

0.1

8.4

1.8

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 49125 Main Street: LEGOLAS_LN Cross Street: LAVETA_RD Location: SW

ADA ID: 59194112E060 Ramp Type: Combination2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

N/A

N/A

N/A

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

No

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

Flare Traversable RT?

Flare Type RT

Ramp XSlope RT (%)

Data

N/A

N/A

N/A

N/A

47.0

47.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A



Street 1 Name

Stop Condition-Street 1

Street 2 Name

None

LEGOLAS LN

N/A

Stop Condition-Street 2

N/A

Possible Solutions:					
Remove & Replace Entire Ramp.					
Surveyor Notes:					
N/A					
PROW/ADA:					
Not Found, R304.5.1, R304.2.2					
4					





Total Cost:



1600.00

	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	Shared Landing?	N/A			
	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.7		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	N/A
	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
/					N/A
	-		Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	14.0