## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10034226	Main Street: PEBBLE_RUN_DR			Cross Street: N/A				Location:	Ν
ADA ID: 5ABDE6F483ED	3ED Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Compli			liance Description	Data	
and the second s		Remove & Replace Curb R	Ramp With	N/A	Ramp Length (in)	49.0	Yes	BlendTrans Slope (%)	1.2
THE PARTY OF		Two New Directional Ram		No	Ramp Width (in)	47.0	Yes	BlendTrans XSlope (%)	0.7
and the second second		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
S. S. S. L. M.				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
STATES STATES				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
State State State	1 to the second	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
PROW/ADA: Not Found, R304.5.1			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	PEBBLE RUN DR	_			X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	1.9		Clear Space?	N/A
					Road X Slope (%)	1.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 3200.0	0	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

18.6