

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 45882 Main Street: HOMESTEAD_GLEN_BV Cross Street: VALLEYDALE_RD Location:	NW			
ADA ID: 5AC0C3DBB7DF Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score:	26.25			
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance				
Possible Solutions: Compliance Description Data Compliance Description	Data			
Remove & Replace Entire Ramp. N/A Ramp Length LT (in) 64.0 N/A Ramp Length RT (in)	56.0			
Yes Ramp Width LT (in) 59.0 Yes Ramp Width RT (in)	60.0			
Yes Ramp Slope LT (%) 5.3 No Ramp Slope RT (%)	12.8			
No Ramp XSlope LT (%) 2.5 No Ramp XSlope RT (%)	3.3			
N/A Ramp Length (in) 47.0 Yes Ramp Slope (%)	3.7			
Yes Ramp Width (in) 50.0 Yes Ramp XSlope (%)	1.6			
Surveyor Notes: N/A Flare Type LT N/A N/A Flare Type RT	N/A			
RP < 5% N/A Flare Slope LT (%) N/A Flare Slope RT (%)	N/A			
N/A Flare Traversable LT? N/A N/A Flare Traversable RT?	N/A			
N/A Landing Length (in) N/A DWS Provided?	N/A			
N/A Landing Width (in) N/A N/A DWS Contrast?	N/A			
PROW/ADA: N/A Landing Slope (%) N/A N/A DWS Length (in)	N/A			
Not Found, R304.5.3, R304.3.2 N/A Landing X Slope (%) N/A N/A DWS Full Width?	N/A			
N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in)	N/A			
N/A Shared Landing? N/A				
N/A Gutter Ponding? N/A N/A Gutter Slope (%)	N/A			
Street 1 Name None N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%)	N/A			
Stop Condition-Street 1 VALLEYDALE RD N/A Painted X Walk1? No N/A Painted X Walk2?	N/A			
Street 2 Name X Walk 1 Direction To SW X Walk 2 Direction	N/A			
Stop Condition-Street 2 N/A X Walk 1 Width (in) N/A X Walk 2 Width (in)	N/A			
X Walk 1 Slope (%) 0.9 X Walk 2 Slope (%)	N/A			
X Walk 1 X Slope (%) <b>2.0</b> X Walk 2 X Slope (%)	N/A			
Total Cost: \$ 1800.00 N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2?	N/A			
Road Slope (%) N/A Clear Space?	N/A			
Road X Slope (%) N/A N/A Clear Space to XWalk (in)	N/A			
N/A Any Obstruction?	N/A			
Obstruction Type				

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

Yes	Surface Condition? (G/P)	Good
	Curb Slope (%)	5.6

N/A





