

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



	0	01				1	014			
Intersection ID: 17758	tersection ID: 17758 Main Street: NATIONS_FORD_RD		Cross	Cross Street: SOUTHWOLD_DR				Location:	SW	
ADA ID: 5BDB6D20313C Ramp Type: Directional1		pe: Directional1		Initial	Initial Pass/Fail: Fail Overall Compliance:			nce: N	o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	いの時間の一時	Possible Solutions:			Compliance Description			Data Compliance Description		
the first	The state	Remove & Replace Entire	Ram	ip.	N/A	Ramp Length (in)	70.0	N/A	Grade Break?	N/A
	101	-		•	Yes	Ramp Width (in)	73.0	N/A	Grade Break Slope (%)	0.0
					Yes	Ramp Slope (%)	4.0	N/A	Grade Break XSlope (%)	0.0
CONTRACTOR DATA	the second second				No	Ramp XSlope (%)	4.5			
a a	Tilling				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
SOUTHWOLD DR					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
		Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
					N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
					N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	福下、」				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	and the second second	R304.5.3			N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	2. 7.3				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
and Cart States					N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	and i				N/A	Painted X Walk1?	No		Road Slope (%)	2.8
Street 1 Name SOU	THWOLD DR					X Walk 1 Direction	To NW		Road X Slope (%)	0.5
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A					X Walk 1 Slope (%)	2.8	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	0.5	N/A	Storm Grate/Utility Hazard?	N/A
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
					N/A	Any Obstructions?	N/A			N/A
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
							N/A	N/A	Curb Slope (%)	10.7

