## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11969	Main Street: BELVEDERE_AV			Street:	THOMAS_AV	Location:	SW		
ADA ID: 5C0CF0C54253	Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:				Compliance Description Data Compliance			liance Description	Data	
	1 All	Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	44.0	No	Ramp Slope (%)	11.1
		Two New Directional Ramps or		Yes	Ramp Width (in)	50.0	Yes	Ramp XSlope (%)	0.0
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1 HELEN			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A. E. D. T.	a good and man			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
BELVEDER		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	k .	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	I THE REAL PROPERTY IN THE REAL	1071		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A	- Marine Car			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	18. 4	the second se		N/A	Shared Landing?	N/A			
	A Long to the second of	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
E Contraction of the second se	COLL - I - I	R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
ALL STREET, ST				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
A State of the second sec					X Walk 1 Direction	To E		X Walk 2 Direction	To N
State - Specific and				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	THOMAS AV	-			X Walk 1 Slope (%)	3.9		X Walk 2 Slope (%)	5.5
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.8		X Walk 2 X Slope (%)	0.1
Street 2 Name	BELVEDERE AV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	3.8	N/A	Clear Space?	N/A
					Road X Slope (%)	4.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

