cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10940	Main Str	Main Street: COLBY_PL			MILTON_RD	Location:	Е		
ADA ID: 5C3AAAB3EC50		Ramp Type: PerpDiag					ompliance: No Severity Score		
			Initian	<u>uss/1 (</u>					10
Codes/Mitigation Info/Possible Solution		Field Measurements/Compone							
A A A A A A A A A A A A A A A A A A A	10	Possible Solutions:		Compliance Description		Data Compliance De			Data
	1//	Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	58.5	Yes	Ramp Slope (%)	7.1
	19 19 19 19 19 19 19 19 19 19 19 19 19 1	Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	41.5		Ramp XSlope (%)	4.8
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
B C B	9			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the the second sec		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
5 K				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	A A M			N/A	Shared Landing?	N/A			
	5.	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R304.5.1, R304.5.				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
E States and the states of the				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
Barrier Barr				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	COBY PL				X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	3.6
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	6.1		X Walk 2 X Slope (%)	1.0
Street 2 Name	MILTON RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	3.3	N/A	Clear Space?	N/A
					Road X Slope (%)	6.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
		•				N/A			N/A
							Yes	Surface Condition? (G/P)	Good
							103		3000