

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14311	Main Street: BERKELEY_AV			Cross Street: CARLTON_AV				Location:	Ν	
ADA ID: 5C784A80C67E	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance:			nce: N	o Severity Score:	25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description D			ata Compliance Description			
	1 1 1	Remove & Replace Entire Ran	מו.	N/A	Ramp Length (in)	68.5	N/A	Grade Break?	N/A	
	1 3012		.6.	Yes	Ramp Width (in)	58.0	N/A	Grade Break Slope (%)	0.0	
				No	Ramp Slope (%)	13.4	N/A	Grade Break XSlope (%)	0.0	
	A			Yes	Ramp XSlope (%)	1.0				
Stand St	The second			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	A ANN	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	A A	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
Box 6	No. AND A			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
AND A CONTRACTOR	Mr.			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
the second	A. M. C. P			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
S. S. S.	Wes . M	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
Et Mar // / Post	A CONT	R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
No. And No.	- Charles	1004.2.2		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	3 and M			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
and the second	and a star			N/A	Painted X Walk1?	No		Road Slope (%)	0.0	
Street 1 Name	CARLTON AV				X Walk 1 Direction	To E		Road X Slope (%)	1.4	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	0.0	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.4	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00	•	Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	12.2	

