

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31501	Main Str	eet: MICHAELS_LANDING_DR	Cross	Street:	UNIVERSITY_CITY_B	v		Location:	SW	
ADA ID: 5C93FC7F5F4				Initial Pass/Fail: Pass Overall Compliance: No						
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance   Compliance Description Data						
	RUP - WAY	Possible Solutions:		Compliance Description			Data Compliance Description			
and water and the	··· · · · · · · · · · · · · · · · · ·	Remove & Replace Entire Ram	).	N/A	Ramp Length (in)	99.0		Grade Break?	N/A	
the second second	and the			Yes	Ramp Width (in)	78.0	N/A	Grade Break Slope (%)	0.0	
A REAL PROPERTY AND INC.	Comment water "Co			Yes	Ramp Slope (%)	4.4	N/A	Grade Break XSlope (%)	0.0	
UNIVERSITY_GITY_EV				Yes	Ramp XSlope (%)	0.4				
				Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A	
- t-t-	J			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
and the second s		Surveyor Notes:		N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
	5. S.	N/A		Yes	Landing Length (in)	54.0	Yes	DWS Provided?	Yes	
				Yes	Landing Width (in)	74.0	Yes	DWS Contrast?	Yes	
			Yes	Landing Slope (%)	0.0	Yes	DWS Length (in)	24.0		
PROW/ADA: Not Found, R305.2				Yes	Landing X Slope (%)	1.1	Yes	DWS Full Width?	Yes	
				N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset LT (in)	40.0	
				N/A	Shared Landing?	No	No	DWS Offset RT (in)	3.0	
				Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.7	
				Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.6	
				N/A	Painted X Walk1?	No		Road Slope (%)	0.5	
Street 1 Name	MICHAELS LANDING DR				X Walk 1 Direction	To E		Road X Slope (%)	1.9	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	Yes	
Street 2 Name	N/A				X Walk 1 Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.9	Yes	Storm Grate/Utility Hazard?	No	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				Yes	Any Obstructions?	No			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	No	Curb Slope (%)	13.7	

