cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28536 Main St	Main Street: SOUTH_STREAM_BV Cross			V_TYVOLA_RD	Location:	SW		
ADA ID: 5D347C48087B Ramp T	mp Type: BlendTrans2 Initial			: Pass Overall	o Severity Score:	15.25		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description			Data Compliance Description		
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.	Vith N/	A	Ramp Length (in)	124.0	Yes	BlendTrans Slope (%)	1.1
		Ye	S	Ramp Width (in)	61.0	No	BlendTrans XSlope (%)	2.1
		N/.	A	Flare Type LT	None	Yes	Flare Type RCurbed_NoWalks	Surface
		N/.	A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N/.	Α	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	No
	1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 19	N/.	A	Landing Length (in)	N/A	No	DWS Provided?	No
	Surveyor Notes:	N/.	A	Landing Width (in)	N/A	N/A	DWS Contrast?	No
	LOCATED ON MEDIAN, SURFACE IS PAVERS	EIS N/	Α	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		_ : • N/.	Α	Landing X Slope (%)	N/A	N/A	DWS Full Width?	No
		N/.		Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
		N/.	Α	Shared Landing?	No		ζ, γ	
	PROW/ADA:	Ye	S	Gutter Ponding?	No	No	Gutter Slope (%)	6.3
	R304.5.3, R305, R304.5.4		s	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.3
				Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name SOUTH STREAM BV	-			X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1 None				X Walk 1 X Slope (%)	0.0		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/.	A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2 N/A				Road Slope (%)	0.0		Clear Space?	Yes
				Road X Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A
		Ye		Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Total Cost: \$ 39	50.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A







Yes

N/A

Surface Condition? (G/P)

Curb Slope (%)

Good

3.0