

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

14.7

\cdot \cdot									
Intersection ID: 18166	tion ID: 18166 Main Street: SCALEYBARK_RD				E WOODLAWN RD	Location:	NW		
ADA ID: 5DC6A3E94378 Ramp Type: Para			Initial Pass	Initial Pass/Fail: Fail Overall Compliance: No					12.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description Data					Data	
	- Ando	Remove & Replace Entire Ramp	N/A	A	Ramp Length LT (in)	65.0	N/A	Ramp Length RT (in)	76.0
			Ye:		Ramp Width LT (in)	60.0		Ramp Width RT (in)	59.0
	The second		Ye	s	Ramp Slope LT (%)	5.9	No	Ramp Slope RT (%)	9.0
			Ye	s	Ramp XSlope LT (%)	1.2	Yes	Ramp XSlope RT (%)	1.1
	1 10 5		N/A	4	Landing Length (in)	N/A		DWS Provided?	N/A
	1 N. Car		N/A	A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
and of the second second	1. Carlos	Surveyor Notes:	N/A	A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
E WOODLAWN RD		N/A	N/A	A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	4	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Contraction of the second seco	L' de -		N/A	A	Shared Landing?	N/A			
	1.		N/A	A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	1	PROW/ADA:	N/A	4	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N. S. M. L. ANDRASS	6	R304.3.2	N/A	A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
at - the second - shares and			N/A	A	X Walk 1 Width (in)	110.0	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A
Street 1 Name E WO	ODLAWN RD	_			X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A
Stop Condition-Street 1	Signal		N/A	A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
Stop Condition-Street 2	N/A				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/#	A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$ 1	600.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good

