

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11464	Main Street: EASTWOOD_DR			Cross Street: SHAMROCK_DR				Location:	W
ADA ID: 5EC949A1B1A1	Ramp Ty	Ramp Type: BlendTrans1			ail: Fail Overall (	o Severity Score:	10		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			ata Compliance Description		Data
		Remove & Replace Curb Ram	p With	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	2.9
		Two New Directional Ramps o		No	Ramp Width (in)	46.0	No	BlendTrans XSlope (%)	3.5
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and the second s		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		NOLNDG		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
The state of the s				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
& Sur		1		N/A	Shared Landing?	N/A			
6		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
6. <b>6</b>		R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	1433			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
8	A COLOR HIS				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
attended to the second				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	SHAMROCK DR	-			X Walk 1 Slope (%)	7.9		X Walk 2 Slope (%)	3.8
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	5.6
Street 2 Name	EASTWOOD DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign				Road Slope (%)	4.0		Clear Space?	N/A
					Road X Slope (%)	10.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					••	N/A			N/A
							1		







Yes

N/A

Surface Condition? (G/P)

Curb Slope (%)

Good

4.4