

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6013 Main Street: BALANCING_ROCK_CT Cross Street: CHIMNEY_ROCK_CT Location: **ADA ID: 5F4E771D5FF0** Ramp Type: Directional1 Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 26.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



CHIMNEY ROCK CT Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A

russible solution			
Possible Solutions:	Co		
Remove & Replace Entire Ramp.			
	Ye		
	No		
	No		
	N/A		
	N/A		
Surveyor Notes:	N/A		
N/A	N/A		
	N/A		
	N/A		
	N/A		
PROW/ADA:	N/A		
R304.2.2, R304.5.3	N/A		

			N
PROW/ADA:			N
R304.2.2, R304.5.3			N
			N
			N
			N
			N
			N
Total Cost:	\$	1600.00	

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	oliance Description	Data			
N/A	Ramp Length (in)	57.0	N/A	Grade Break?	N/A			
Yes	Ramp Width (in)	54.0	N/A	Grade Break Slope (%)	0.0			
No	Ramp Slope (%)	13.4	N/A	Grade Break XSlope (%)	0.0			
No	Ramp XSlope (%)	3.1						
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A			
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A			
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	No		Road Slope (%)	3.7			
	X Walk 1 Direction	To N		Road X Slope (%)	0.4			
	X Walk 1 Width (in)	N/A		Clear Space?	N/A			
	X Walk 1 Slope (%)	3.7	N/A	Clear Space to XWalk (in)	N/A			
	X Walk 1 X Slope (%)	0.4	N/A	Storm Grate/Utility Hazard?	N/A			
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type				
N/A	Any Obstructions?	N/A			N/A			
	Obstruction Type		Yes	Surface Condition? (G/P)	Good			
		N/A	N/A	Curb Slope (%)	16.3			
			-					





