cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 51701 Main Street: STEELECROFT_PY Cross Street: HOOVER_CREEK_BV							Location:	NE
ADA ID: 5F5C60A97650 Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Complian			nce: N	o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
	Possible Solutions:		Compliance Description			Data Compliance Description		
	Remove & Replace Curb Ramp W	/ith N//	Α	Ramp Length (in)	96.0	No	Ramp Slope (%)	9.0
the second of the second second	Two New Directional Ramps or	Ye	S	Ramp Width (in)	50.0	No	Ramp XSlope (%)	3.2
	Equivalent.	N//	A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N//	Α	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N//	Α	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/.	Α	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N//	Α	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N//	Α	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/2	A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N//	A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
STEELEGROFT_PY		N//	Α	Shared Landing?	N/A			
2 10 10	PROW/ADA:	N//	Α	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
The second second	Not Found, R304.2.2, R304.5.3	N//	A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	·····, ·····, ·····, ······, ·····	N/2	Α	Painted X Walk1?	No	N/A	Painted X Walk2?	No
a for a				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
		N//	Α	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name HOOVER CREEK BV	-			X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	0.7
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	2.3
Street 2 Name STEELECROFT PY		N/.	A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 StopSign				Road Slope (%)	1.7	N/A	Clear Space?	N/A
				Road X Slope (%)	1.4	N/A	Clear Space to XWalk (in)	N/A
		N/	Α	Any Obstructions?		N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
	•			21	N/A			N/A
						Yes	Surface Condition? (G/P)	Good

Ball