cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 49392	49392 Main Street: HEREFORD_ST			Street:	AUBRAC_LN	Location:	NE		
ADA ID: 5F89A8F642DB	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data			Compliance Description		Data
		Remove & Replace Curb Ram	n With	N/A	Ramp Length (in)	70.5	Yes	BlendTrans Slope (%)	4.9
		Two New Directional Ramps of	-	No	Ramp Width (in)	47.5		BlendTrans XSlope (%)	4.1
		Equivalent.		N/A	Flare Type LT	N/A		Flare Type RT	N/A
		-		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
	- F.H &	1		N/A	Landing Length (in)	N/A		DWS Provided?	N/A
	ERAG_LIN	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E E AUER		N/A		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second second				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
and second the same				N/A	Shared Landing?	N/A		Dwe enset (iii)	10/0
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Tre			N/A	•	N/A		,	N/A
		Not Found, R304.5.1, R304.5.3	5	N/A	Gutter Lip Ht (in) Painted X Walk1?	N/A No	N/A	Gutter X Slope (%) Painted X Walk2?	N/A No
			N/A		-	N/A		-	
Towns					X Walk 1 Direction	To W		X Walk 2 Direction	To S
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	HEREFORD ST				X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	3.6
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	3.3		X Walk 2 X Slope (%)	2.1
Street 2 Name	AUBRAC LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	3.1		Clear Space?	N/A
					Road X Slope (%)	4.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

31.4