

Access Compliance Report


Public Rights-of-Way

(Curb Ramps)

Intersection ID: 42489	Main Street: ALEXANDER MARTIN AV	Cross Street: LINA ARDREY LN	Location: NE
ADA ID: 5FDACAFCD0B3	Ramp Type: Combination1Diag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 0	

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

RP & RT RP < 5%

PROW/ADA:

R304.5.1, R304.5.3

Street 1 Name **None**
 Stop Condition-Street 1 **ALEXANDER MARTIN AV**
 Street 2 Name **StopSign**
 Stop Condition-Street 2 **LINA ARDREY LN**

Total Cost: \$ **3200.00**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	30.5	N/A	Ramp Length RT (in)	21.0
Yes	Ramp Width LT (in)	62.5	Yes	Ramp Width RT (in)	62.5
Yes	Ramp Slope LT (%)	8.3	Yes	Ramp Slope RT (%)	1.3
No	Ramp XSlope LT (%)	2.6	No	Ramp XSlope RT (%)	2.6
N/A	Ramp Length (in)	41.0	Yes	Ramp Slope (%)	3.6
No	Ramp Width (in)	37.0	No	Ramp XSlope (%)	4.5
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	0.4
	X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	2.6
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	3.4		Clear Space?	N/A
	Road X Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	N/A
Yes	Surface Condition? (G/P)	Good			
	Curb Slope (%)	0.6			

