

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 5980 Main Street: SUTHER RD Cross Street: MARGIE\_ANN\_DR Location: ADA ID: 5FDF66F9BDA7 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 8.75

**Codes/Mitigation Info/Possible Solution** 



Street 1 Name **MARGIE ANN DR** Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1

Total Cost: 1850.00

| Field Measurements/Component Compliance |                       |      |     |                             |      |
|---|-----------------------|------|-----|-----------------------------|------|
|   | liance Description    | Data |     | liance Description          | Data |
| N/A                                     | Ramp Length (in)      | 22.0 | Yes | Ramp Slope (%)              | 7.4  |
| No                                      | Ramp Width (in)       | 45.0 | Yes | Ramp XSlope (%)             | 0.3  |
| N/A                                     | Flare Type LT         | N/A  | N/A | Flare Type RT               | N/A  |
| N/A                                     | Flare Slope LT (%)    | N/A  | N/A | Flare Slope RT (%)          | N/A  |
| N/A                                     | Flare Traversable LT? | N/A  | N/A | Flare Traversable RT?       | N/A  |
| N/A                                     | Landing Length (in)   | N/A  | N/A | DWS Provided?               | N/A  |
| N/A                                     | Landing Width (in)    | N/A  | N/A | DWS Contrast?               | N/A  |
| N/A                                     | Landing Slope (%)     | N/A  | N/A | DWS Length (in)             | N/A  |
| N/A                                     | Landing X Slope (%)   | N/A  | N/A | DWS Full Width?             | N/A  |
| N/A                                     | Landing Curb? (Y/N)   | N/A  | N/A | DWS Offset (in)             | N/A  |
| N/A                                     | Shared Landing?       | N/A  |     |                             |      |
| N/A                                     | Gutter Ponding?       | N/A  | N/A | Gutter Slope (%)            | N/A  |
| N/A                                     | Gutter Lip Ht (in)    | N/A  | N/A | Gutter X Slope (%)          | N/A  |
| N/A                                     | Painted X Walk1?      | No   | N/A | Painted X Walk2?            | N/A  |
|   | X Walk 1 Direction    | To E |     | X Walk 2 Direction          | N/A  |
| N/A                                     | X Walk 1 Width (in)   | N/A  | N/A | X Walk 2 Width (in)         | N/A  |
|   | X Walk 1 Slope (%)    | 4.5  |     | X Walk 2 Slope (%)          | N/A  |
|   | X Walk 1 X Slope (%)  | 5.9  |     | X Walk 2 X Slope (%)        | N/A  |
| N/A                                     | Ramp inside XWalk1?   | N/A  | N/A | Ramp inside XWalk2?         | N/A  |
|   | Road Slope (%)        | N/A  | N/A | Clear Space?                | N/A  |
|   | Road X Slope (%)      | N/A  | N/A | Clear Space to XWalk (in)   | N/A  |
| N/A                                     | Any Obstructions?     | N/A  | N/A | Storm Grate/Utility Hazard? | N/A  |
|   | Obstruction Type      |      |     | Storm Grate/Utility Type    |      |
|   |                       | N/A  |     |                             | N/A  |
|   |                       |      | Yes | Surface Condition? (G/P)    | Good |
|   |                       |      |     |                             |      |





