

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

16.7

2.8

N/A

Good

Intersection ID: 2928 Main Street: PROSPERITY_CHURCH_RD Cross Street: RIDGE_RD Location: SE

ADA ID: 5FF9DCC45C65 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 26.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Flare Type RT

Data

188.0

48.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

No

To N

N/A

4.6

3.2

N/A

N/A

N/A

N/A

N/A



Street 1 Name	RIDGE RD
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

OSSIDIE SOIGLION		i iciu ivicas
Possible Solutions:	Comp	liance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
·	Yes	Ramp Width (in)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable LT?
	N/A	Landing Length (in)
Surveyor Notes:	N/A	Landing Width (in)
N/A	N/A	Landing Slope (%)
	N/A	Landing X Slope (%)
	N/A	Landing Curb? (Y/N)
	N/A	Shared Landing?
PROW/ADA:	N/A	Gutter Ponding?
N/A	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
	N/A	X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%)
	N/A	Ramp inside XWalk1?
		Road Slope (%)
		Road X Slope (%)





Total Cost:



N/A

1850.00

Any Obstructions?

Obstruction Type