

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8908 Main Street: RUSSELL\_AV Cross Street: WELCH\_PL Location: SW

ADA ID: 604467C34D92 Ramp Type: BlendTrans2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance



Street 1 Name

Stop Condition-Street 1

StopSign

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
NO LT SW

PROW/ADA:
Not Found, R304.5.3

Total Cost: \$ 3200.00

| Field Measurements/Component Compliance |                        |                       |      |                          |                             |      |
|---|------------------------|-----------------------|------|--------------------------|-----------------------------|------|
|   | Compliance Description |                       | Data | a Compliance Description |                             | Data |
|   | N/A                    | Ramp Length (in)      | 59.5 | Yes                      | BlendTrans Slope (%)        | 3.3  |
|   | Yes                    | Ramp Width (in)       | 71.0 | No                       | BlendTrans XSlope (%)       | 6.2  |
|   | N/A                    | Flare Type LT         | N/A  | N/A                      | Flare Type RT               | N/A  |
|   | N/A                    | Flare Slope LT (%)    | N/A  | N/A                      | Flare Slope RT (%)          | N/A  |
|   | N/A                    | Flare Traversable LT? | N/A  | N/A                      | Flare Traversable RT?       | N/A  |
|   | N/A                    | Landing Length (in)   | N/A  | N/A                      | DWS Provided?               | N/A  |
|   | N/A                    | Landing Width (in)    | N/A  | N/A                      | DWS Contrast?               | N/A  |
|   | N/A                    | Landing Slope (%)     | N/A  | N/A                      | DWS Length (in)             | N/A  |
|   | N/A                    | Landing X Slope (%)   | N/A  | N/A                      | DWS Full Width?             | N/A  |
|   | N/A                    | Landing Curb? (Y/N)   | N/A  | N/A                      | DWS Offset (in)             | N/A  |
|   | N/A                    | Shared Landing?       | N/A  |                          |                             |      |
|   | N/A                    | Gutter Ponding?       | N/A  | N/A                      | Gutter Slope (%)            | N/A  |
|   | N/A                    | Gutter Lip Ht (in)    | N/A  | N/A                      | Gutter X Slope (%)          | N/A  |
|   | N/A                    | Painted X Walk1?      | No   | N/A                      | Painted X Walk2?            | N/A  |
|   |                        | X Walk 1 Direction    | To E |                          | X Walk 2 Direction          | N/A  |
|   |                        | X Walk 1 Width (in)   | N/A  |                          | X Walk 2 Width (in)         | N/A  |
|   |                        | X Walk 1 Slope (%)    | 0.5  |                          | X Walk 2 Slope (%)          | N/A  |
|   |                        | X Walk 1 X Slope (%)  | 2.8  |                          | X Walk 2 X Slope (%)        | N/A  |
|   | N/A                    | Ramp inside XWalk1?   | N/A  | N/A                      | Ramp inside XWalk2?         | N/A  |
|   |                        | Road Slope (%)        | 2.8  |                          | Clear Space?                | N/A  |
|   |                        | Road X Slope (%)      | 0.5  | N/A                      | Clear Space to XWalk (in)   | N/A  |
|   | N/A                    | Any Obstructions?     | N/A  | N/A                      | Storm Grate/Utility Hazard? | N/A  |
|   |                        | Obstruction Type      |      |                          | Storm Grate/Utility Type    |      |
|   |                        |                       | N/A  |                          |                             | N/A  |
|   |                        |                       |      | Yes                      | Surface Condition? (G/P)    | Good |
|   |                        |                       |      | No                       | Curb Slope (%)              | 23.1 |
|   |                        |                       |      |                          |                             |      |





