

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 26235	Main Street: COLMAR_LN			Street:	GLEN_SUMMIT_D	Location:	NE			
ADA ID: 614E8E99A538	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
AND		Possible Solutions:		Compliance Description Data Compli				liance Description	Data	
and the second		Remove & Replace Entire Ram	).	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	6.8	
the state of the second	MA PI	······	-	Yes	Ramp Width (in)	49.0	No	Ramp XSlope (%)	6.6	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Parties and and	Quere All	1		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
the second	Man d.			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
10 A 100	10-	-		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	and the second s	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
THE DE		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
SUMMU	2 MAN IN A PROPERTY			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
ELELLE (	1 1 - 1 S			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
a la	1 1 M			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
2.	B C C C C	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
11/ 6	TE SAN			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	114				X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	GLEN SUMMIT DR				X Walk 1 Slope (%)	7.8		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.5		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	1.5	N/A	Clear Space?	N/A	
					Road X Slope (%)	7.8	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

