cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

12.5

Intersection ID: 10022801 Main Street: CASCADE_POINTE_BV				Street:	N/A	Location:	SW		
ADA ID: 64627F9103D4 Ramp Type: ParaDiag				itial Pass/Fail: Fail Overall Compliance: No				Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Complian			liance Description	Data	
		Remove & Replace Curb Ramp \	Nith	N/A	Ramp Length LT (in)	35.0	N/A	Ramp Length RT (in)	72.0
		Two New Directional Ramps or		Yes	Ramp Width LT (in)	86.0	Yes	Ramp Width RT (in)	66.0
E.		Equivalent.		Yes	Ramp Slope LT (%)	7.2	No	Ramp Slope RT (%)	8.6
9	N. Br			Yes	Ramp XSlope LT (%)	0.6	Yes	Ramp XSlope RT (%)	1.4
Contraction (Contraction)	E. A. B.			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
5				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	200	Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
the state of the second	No.	N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	KIN I			N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
the water is a set	1 / 189	PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	A CONTRACTOR	R304.3.2		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To NE		X Walk 2 Direction	To NW	
The second second second				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	4.3		X Walk 2 Slope (%)	1.6
Street 1 Name CAS	SCADE POINTE BV				X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	3.7
Stop Condition-Street 1	None			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	ENTRANCE				Road Slope (%)	1.0	N/A	Clear Space?	N/A
Stop Condition-Street 2	None				Road X Slope (%)	5.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$ 3	200.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good

