

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.6

2.3

N/A

Good

Intersection ID: N/A Main Street: INVERNESS BAY RD Cross Street: ELGIN MOOR RD Location: NE **Overall Compliance: No Severity Score:** 22.5 ADA ID: 64C921CE649E Ramp Type: Perp Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

48.0

46.5

N/A

1.0

No

N/A

0.6

3.3

N/A

N/A

N/A

N/A

N/A

To NW

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?



INVERNESS BAY RD Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solutions:	Compliance Description
Remove & Replace Entire Ramp.	N/A Ramp Length (in)
	No Ramp Width (in)
	N/A Flare Type LT
	N/A Flare Slope LT (%)
	N/A Flare Traversable L
	N/A Landing Length (in)
Surveyor Notes:	N/A Landing Width (in)
N/A	N/A Landing Slope (%)
	N/A Landing X Slope (%
	N/A Landing Curb? (Y/N
	N/A Shared Landing?
PROW/ADA:	N/A Gutter Ponding?
Not Found, R304.5.1, R304.2.2	N/A Gutter Lip Ht (in)
	N/A Painted X Walk1?
	X Walk 1 Direction
	N/A X Walk 1 Width (in)
	X Walk 1 Slope (%)
	X Walk 1 X Slope (%
	N/A Ramp inside XWalk





Total Cost:



N/A

1850.00