

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12918Main Street:CLEMENT\_AVCross Street:HAMORTON\_PLLocation:NEADA ID: 64F6B436DAC0Ramp Type:PerpendicularInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

**Codes/Mitigation Info/Possible Solution** 



AND THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.	A STATE OF THE PARTY OF THE PAR
Street 1 Name	HAMORTON PL
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

n ossible solution		
Possible Solutions:	Comp	lianc
Remove & Replace Entire Ramp.	N/A	Ra
	No	Ra
	N/A	Fla
	N/A	Fla
	N/A	Fla
	N/A	La
Surveyor Notes:	N/A	La
N/A	N/A	La
	N/A	La
	N/A	La
	N/A	Sh
PROW/ADA:	N/A	Gι
Not Found, R304.5.1, R304.5.3	N/A	Gι
	N/A	Pa
		X١
	N/A	X١
		X١
		X١
	N/A	Ra
		Ro
		Ro

	A WAR AND A STATE OF THE STATE	
	h	
A W		
		And Development
		*12.0



Total Cost:



1850.00

Field Measurements/Component Compliance						
Compl	iance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	60.0	Yes	Ramp Slope (%)	6.9	
No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	2.1	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
7 20			Yes	Surface Condition? (G/P)	Good	