cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11707	1707 Main Street: N_GRAHAM_ST			Cross Street: W_6TH_ST				Location:	Е
ADA ID: 657F8837DB6D	Ramp T	Ramp Type: BlendTrans1			ail: Pass Overall	o Severity Score:	25.25		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	5 .	Possible Solutions:		Compliance Description		Data Compliance Description		Data	
		Remove & Replace Curb Ram	p With	N/A	Ramp Length (in)	24.0	Yes	BlendTrans Slope (%)	3.8
		Two New Directional Ramps o		Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	2.6
		Equivalent. Remove & Replace Gutter.	e	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
				No	Flare Slope LT (%)	16.7	Yes	Flare Slope RT (%)	9.7
				N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
6.6. AND				Yes	Landing Length (in)	53.0	Yes	DWS Provided?	Yes
		Surveyor Notes:		Yes	Landing Width (in)	76.0	Yes	DWS Contrast?	Yes
		LOCATED ON MEDIAN		Yes	Landing Slope (%)	1.9	Yes	DWS Length (in)	24.0
				No	Landing X Slope (%)	3.4	Yes	DWS Full Width?	Yes
	4		N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0	
	47			N/A	Shared Landing?	Yes			
	1168	PROW/ADA:		No	Gutter Ponding?	Yes	No	Gutter Slope (%)	6.8
CAR ARTIN		Not Found, R304.5.3, R304.2.3, R302.7, R302.7.2, R304.5.4		No	Gutter Lip Ht (in)	1.0	Yes	Gutter X Slope (%)	1.7
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
					X Walk 1 Width (in)	78.0		X Walk 2 Width (in)	N/A
Street 1 Name	W 6TH ST	_			X Walk 1 Slope (%)	3.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	Signal				X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	2.5		Clear Space?	Yes
					Road X Slope (%)	3.4	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$	3950.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

9.2