

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 8757		Main Street: JENNINGS_ST		Cross Street: NEWCASTLE_ST		Location: S											
ADA ID: 659C857EE01C		Ramp Type: Directional2		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 0									
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance													
 Street 1 NameJENNINGS ST Stop Condition-Street 1None Street 2 NameN/A Stop Condition-Street 2N/A				Possible Solutions:		Compliance		Description		Data		Compliance		Description		Data	
				Remove & Replace Entire Ramp. Remove & Replace Gutter.		N/A	Ramp Length (in)	49.5		Yes	Grade Break?	Yes					
						Yes	Ramp Width (in)	48.0		Yes	Grade Break Slope (%)	1.7					
						Yes	Ramp Slope (%)	7.3		Yes	Grade Break XSlope (%)	1.1					
						Yes	Ramp XSlope (%)	0.7									
						N/A	Flare Type LT	N/A		Yes	Flare Type RT	N/A					
				Surveyor Notes: N/A		N/A	Flare Slope LT (%)	N/A		N/A	Flare Slope RT (%)	N/A					
						N/A	Flare Traversable LT?	N/A		N/A	Flare Traversable RT?	No					
						No	Landing Length (in)	37.0		Yes	DWS Provided?	Yes					
						Yes	Landing Width (in)	57.5		Yes	DWS Contrast?	Yes					
Yes	Landing Slope (%)	0.4				Yes	DWS Length (in)	24.5									
Yes	Landing X Slope (%)	1.7				Yes	DWS Full Width?	Yes									
N/A	Landing Curb? (Y/N)	N/A				Yes	DWS Offset LT (in)	0.0									
N/A	Shared Landing?	No				No	DWS Offset RT (in)	80.0									
Yes	Gutter Ponding?	No				Yes	Gutter Slope (%)	3.8									
Yes	Gutter Lip Ht (in)	0.0				No	Gutter X Slope (%)	2.5									
PROW/ADA: Not Found, R304.2.1, R305.2, R304.5.3		N/A	Painted X Walk1?	No			Road Slope (%)	5.6									
			X Walk 1 Direction	To W			Road X Slope (%)	1.8									
			X Walk 1 Width (in)	N/A			Clear Space?	Yes									
			X Walk 1 Slope (%)	5.6		N/A	Clear Space to XWalk (in)	N/A									
			X Walk 1 X Slope (%)	1.8		Yes	Storm Grate/Utility Hazard?	No									
		N/A	Ramp inside XWalk1?	N/A			Storm Grate/Utility Type										
		Yes	Any Obstructions?	No				N/A									
			Obstruction Type			Yes	Surface Condition? (G/P)	Good									
						N/A	Curb Slope (%)	18.4									

