cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



									/	
Intersection ID: 2862	5 Main Street: GREYBRIAR_FOREST_LN Cro				ss Street: PEDLAR_MILLS_RD			Location:	NE	
ADA ID: 664769A9D0	51 Ramp T	Ramp Type: BlendTrans1 Initi			al Pass/Fail: Fail Overall Compliance: No			o Severity Score:	17.5	
	Codes/Mitigation Info		Field Measurements/Component Compliance							
		Possible Solutions:		Com				ta Compliance Description		
		Remove & Replace Curb R	omn Wit		Ramp Length (in)	47.3	Yes	BlendTrans Slope (%)	Data 3.3	
		Two New Directional Ramp	•	No	Ramp Width (in)	34.0	Yes	BlendTrans XSlope (%)	3.3 1.1	
		Equivalent.	5 01	N/A	Flare Type LT	N/A		Flare Type RT	N/A	
				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A N/A	
					Flare Traversable LT?			Flare Traversable RT?	N/A N/A	
	1 Toma			N/A		N/A				
	Con Lind			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
e.		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
- Nacional and Contraction of Con-		N/A		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A	
a come		1		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	ROP	3		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	AND THE AND			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To W		X Walk 2 Direction	To S	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	PEDLAR MILLS RD				X Walk 1 Slope (%)	5.9		X Walk 2 Slope (%)	1.8	
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	1.3	
Street 2 Name	GREYBRIAR FOREST LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	None				Road Slope (%)	1.4		Clear Space?	N/A	
					Road X Slope (%)	3.8	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.		Obstruction Type			Storm Grate/Utility Type		
		••••••••••••••••••••••••••••••••••••••	0200			N/A			N/A	
						13/A			10/5	

YesSurface Condition? (G/P)NoCurb Slope (%)

Good

53.7





