

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 45061	Main Str	Main Street: EVANGELION_CT			Street:	REDDING_GLEN_AV	Location:	SE		
ADA ID: 67C9BB022BDB	B Ramp Ty	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	PH	Possible Solutions:			Compliance Description		Data Compliar		ance Description	Data
		Remove & Replace Cur	b Ram	with	N/A	Ramp Length (in)	47.0	Yes	BlendTrans Slope (%)	4.4
		Two New Directional Ra	•	•	No	Ramp Width (in)	47.0	No	BlendTrans XSlope (%)	2.7
The second		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	Jan 13				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	ALENAN				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
El	DDING OF	Surveyor Notes:			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
E . E .	Walk				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
G.	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
6.				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A				
	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1, F	2304 5	3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
A Start and			Ū	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
A LA						X Walk 1 Direction	To N		X Walk 2 Direction	To W
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	EVANGELION CT	-				X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	0.1
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	0.1
Street 2 Name	REDDING GLEN AV				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign					, Road Slope (%)	4.0		Clear Space?	N/A
						Road X Slope (%)	0.8	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
			•			51	N/A			N/A
								1		







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

14.3