

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14177	Main Str	Cross Street: TWO_MOONS_DR					Location:	SW		
ADA ID: 68CB428CEA41	Ramp Ty	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				8.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	ALL X	Possible Solutions:		Compliance Description Da			ta Compliance Description		Data	
and the state		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	61.0	N/A	Grade Break?	N/A	
				No	Ramp Width (in)	47.0	N/A	Grade Break Slope (%)	0.0	
and the second s				Yes	Ramp Slope (%)	7.7	N/A	Grade Break XSlope (%)	0.0	
	Sted P. M.			Yes	Ramp XSlope (%)	1.9				
BARON				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
De state				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
<b>E</b> ./.	Salar Street and the second	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	A State of the second second			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
C D's				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
and the second sec	Stor 1	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
and a second sec	Mr. No	R304.5.1		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
- ADD				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	1 2 2 4			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
Contraction of the	C 234 23			N/A	Painted X Walk1?	No		Road Slope (%)	3.1	
Street 1 Name	TWO MOONS DR				X Walk 1 Direction	To E		Road X Slope (%)	5.8	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	3.1	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	5.8	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	15.2	

